

REMOVE

SMOOTH




FINISH

POLISH

GENERAL GUIDELINES FOR E-Z LOC® BRUSHES & TA DISCS							
	36 (A/O)	50 (A/O)	80 (A/O)	120 (A/O)	220 (A/O)	400 (A/O)	
METAL	IRON					EXCLUSIVE TO SUNBURST	
	STEEL						
	ALUMINUM						
	NON-FERROUS						
TASK	CLEANING & SURFACE CONTAMINANT REMOVAL						
	AGGRESSIVE	HEAVY DUTY	STANDARD	LIGHT DUTY			
	Adhesives • Coatings • Corrosion • Glue • Oxidation • Paint • Rust • Sealant • Stains Varnish • Weld Burns • Weld Discoloration						
	MILL SCALE REMOVAL						
	HEAVY DUTY		LIGHT DUTY		A cleaner surface enables better adhesion of subsequent coatings		
Aluminum • Steel • Non-Ferrous							
COMMON USE CASES	Welding		Auto Repair/Restoration		How do YOU use E-Z Loc? We'd love to see it. Send images, videos or links to: service@dedeco.com		
	- Clean and prep surface - Removal of weld burn, splatter and discoloration		- Surface conditioning, blend out scratches and defects - Gasket removal - Tire adhesive removal				

QUICK CHANGE



Use on right angle grinders, CNC and robotic applications

